




Spare screws for goniometer heads

Goniometer head	Pin	Scale	Fixation	Tilt
1001	1000-1/	/	/	/
1002	1000-21000-54x	1000-4/		
1003	/	/	/	/
1004	1000-21000-52x	1000-3 /		
1005	1000-21000-54x	1000-4 /		
1006	/	/	/	/
1007	1000-5/	2x 1000-34x	1000-1	

Fitting spare screws:

The following illustrations should help in identifying the right screws:


Spare screw for specimen carrier/pin:



Spare screw for scale:



Spare screw for clamping:



Spare screw for tilt:



