



## Thread rings and bases for goniometer heads

---

Thread rings and bases for goniometer heads IUCR standard

As spare part or for special applications

### Thread ring type 1001-1

---



Fitting for:

- 1001
- 1003
- 1004
- 1006

### Thread ring type 1002-1

---



Fitting for:

- 1002
- 1005

### Base type 1002-2

---



Fitting for:

- 1002

Base type 1003-2

---



Fitting for:

- 1003

Base type 1005-2

---



Fitting for:

- 1005

## Base type 1006-2

---



Fitting for:

- 1006

