




## Goniometer Head 1001



|                       |              |
|-----------------------|--------------|
| Adjustable axes:      | X, Y, Ry, Rx |
| Range X [mm]:         | +/- 4.5      |
| Range Y [mm]:         | +/- 4.5      |
| Range Ry [°]:         | +/- 22       |
| Range Rx [°]:         | +/- 25       |
| Height [mm]:          | 64           |
| Read-out accuracy[°]: | 0.1          |
| Weight [kg]:          | 0.2          |

## Included:

- adjustment pin
- goniometer head key
- storage box
- adhesive wax
- 2x sample carrier

